



Joint Environmental Training Coordinating Committee

Winter/Spring 2017 JETCC Training Schedule

DATE	COURSE TITLE	LOCATION	HOURS
February 21	PVC Valves, Connections, and Joining <i>Sponsored by Spears Manufacturing</i>	Waterville	*6
February 23	PVC Valves, Connections, and Joining <i>Sponsored by Spears Manufacturing</i>	Kennebunkport	*6
March 1	Things That Make The World Turn: Bearings, Motors, Pumps, VFDs <i>Sponsored by Motion Industries</i>	Augusta	*6
March 7	Basic Chemistry for Operators <i>In cooperation with RCAP Solutions</i>	Bangor	*3.5
March 15-17	O & M of Wastewater Collection Systems (w/optional NEWEA Exam).... <i>In cooperation with NEIWPC</i>	Portland	15
March 21	Pump Maintenance and Troubleshooting.....	York	*6
March 22	Motors, Controls, & Electrical Schematics with Hands-on Wiring	Boothbay	*6
March 23	Pump Maintenance and Troubleshooting.....	Fairfield	*6
March 23	Water & Wastewater Microbiology and Bacteria Tests..... <i>Sponsored by Idexx Industries</i>	Westbrook	*6
March 30	Math Review with Strategies for Operator Certification Exam Success...	Bangor	*6
April 19	Overview of Drinking Water Distribution Systems..... <i>Approved for DW Operators Only</i>	Portland	*6
April 25	Biological Nutrient Removal (BNR) <i>Presented by Michael H. Gerardi</i>	Wells	6
April 26 & 27	North Country Convention	Presque Isle	*12
May 9	Collection System Diagnosis & Maintenance Series: Part two - Inspections..... <i>In cooperation with MeWEA WWCS Committee</i>	Fairfield	6
May 16	Confined Space Entry, Line Locating, and Equipment Review	Farmington	*6

Unless noted, all programs are approved by Maine DEP for Wastewater Operator certification renewal.

*Programs are also approved by Maine Board of Licensure of Water System Operators.

Special thanks to Maine Water Environment Association (MEWEA) for help in defraying our printing costs.

Maine JETCC is managed by the New England Interstate Water Pollution Control Commission (NEIWPC) through a contract with the Maine Department of Environmental Protection.

For course details, visit www.jetcc.org

Tuesday, February 21, 2017

PVC Valves, Connections, and Joining

8:30 a.m. - 3:30 p.m.

Sign-in begins at 8:00 a.m.

KENNEBEC SANITARY TREATMENT DISTRICT

401 Water St.

Waterville, ME

(207) 873-0611

FROM SOUTH: Travel I-95 and take Exit 127 (Oakland – Kennedy Memorial Drive). Turn RIGHT at light at end of exit ramp onto Kennedy Memorial Drive (KMD) going towards Waterville. Proceed east on KMD for ~ 1.5 miles (6 traffic lights).

Move to right hand lane at 6th light (West River Rd.) and take the ramp for the Carter Memorial Bridge. Move to left lane immediately after ramp and take the first left (Grove St.). Drive to the end of Grove St. ~ ½ mile to Water St.

Turn right onto Water St. and drive 1 mile, the main building is directly ahead, the KSTD main entrance is the driveway bearing to the right.

FROM NORTH: Travel I-95 and take Exit 127 (Oakland – Kennedy Memorial Drive). Turn LEFT at light at end of exit ramp onto Kennedy Memorial Drive (KMD) going towards Waterville. Proceed east on KMD for ~ 1.6 miles (7 traffic lights).

Move to right hand lane at 7th light (West River Rd.) and take the ramp for the Carter Memorial Bridge. Move to left lane immediately after ramp and take the first left (Grove St.). Drive to the end of Grove St. ~ ½ mile to Water St.

Turn right onto Water St. and drive 1 mile, the main building is directly ahead, the KSTD main entrance is the driveway bearing to the right.

Thursday, February 23, 2017

PVC Valves, Connections, and Joining

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

KENNEBUNKPORT FIRE STATION
32 North Street
Kennebunkport, ME
(207) 967-2245

Southbound on Maine Turnpike: Get off the Turnpike at Exit 32 Biddeford. Go straight across Route 111 and on to the Connector Rd. to Route 1 South. At the end of the Connector Rd. (.9 miles from the turnpike) take Route 1 South. Go 3.5 miles south on Route 1 until you come to the first traffic light and take a left onto the Log Cabin Road in Arundel. On the Log Cabin Road and then onto North St. (4.8 miles from Route 1) you come to the fire station and the town parking lot.

Northbound on Maine Turnpike: Get off at Wells Exit 19. Go left on Route 9 for 1.6 miles to Route 1 North. Take a left on Route 1 North for 1.7 miles to Route 9 East. Take the right on Route 9 E for 4.2 miles on Route 9 to the second traffic light. Go straight through the light across the bridge through Dock Square, (.4 miles from the traffic light) to the stop signs. Take a left at stop sign and go .3 mile to the town parking lot and the fire station.

Wednesday, March 1, 2017

Things That Make the World Turn: Bearings, Motors, Pumps, VFDs

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

AUGUSTA CIVIC CENTER
110 Community Drive
Augusta, ME
(207) 626-2405

From north on I-95 take Exit 112. From south on I-95 take Exit 112A.

You can see the civic center from the exit. Take right into parking lot. Look for directions to meeting room on inside sign.

Tuesday, March 7, 2017

Basic Chemistry for Operators

8:00 a.m. - 12:00 p.m.
Sign-in begins at 7:30 a.m.

BANGOR WATER POLLUTION CONTROL FACILITY
760 Main Street
Bangor, ME
(207) 942-4111

From I-95: Get off Bangor/Brewer Exit onto Route 395. Get off at the Farm Road Exit 3A. Take left at stop sign onto Farm Rd. Go approximately 100 yards. Take a right at the stop sign (by the Armory) onto Main St. Go underneath railroad overpass - WWTP on the left. Go to the Administration Building.

Wednesday-Friday, March 15 through 17, 2017

O&M of Wastewater Collection Systems

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

Jeff Nixon Development Center
PORTLAND WATER DISTRICT OFFICES
225 Douglass Street
Portland, ME
(207) 774-5961

Southbound from I-295:

Take the Congress St. Exit 5B. Turn right onto Congress Street then immediately take first right onto Douglass St. (Johnson's Sporting Goods on corner of Congress and Douglass Streets). Go to the end. Parking lot is across the street from the training center.

Northbound from I-295: Take Congress St. Exit. After exit, move immediately into right lane and stay right around the clover leaf towards Transportation Center. At end of ramp, stay right onto Fore River Parkway. Go straight through one set of lights and continue on Fore River Parkway to end. **(Hint: Stay in the middle lane because just ahead the two left lanes will have left arrows onto Congress Street, you will want to be in the outside left turning lane).** Turn left on Congress Street then immediately take the first right onto Douglass St. (Johnson's Sporting Goods on corner of Congress and Douglass Streets). Go to the end. Parking lot is across the street from the training center.

Tuesday, March 21, 2017

Pump Maintenance and Troubleshooting

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

YORK SEWER DISTRICT
Maintenance Building
21 Bay Haven Road
York, ME
(207) 363-4232

From I-95 Maine Turnpike: Take Exit 7 toward York/The Berwicks and turn left at the fork and follow signs to York/South Berwick. Turn left towards Route One, then turn left onto U.S. Route One North. Drive approximately 3 miles, then turn right onto Cape Neddick Road. Turn right onto Shore Road then turn left on Bay Haven Road. Entrance to the York Sewer District will be on the right.

Wednesday, March 22, 2017

Motors, Controls, and Electrical Schematics With Hands-on Wiring

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

BOOTHBAY FIRE STATION
911 Wiscasset Road (Route 27)
Boothbay, Maine
633-4663 or 380-4663

Traveling North – From Maine Turnpike I-95 take Exit 6 to 295 north. Continue on 295 approximately 26 miles and take exit 28 for US-1 toward Bath/Brunswick/ Coastal Route. Stay right toward US 1- North and continue north on Rte 1 approx 23.5 miles. Turn right at Boothbay Road/ Rte 27 and continue approximately 9 miles. You cannot miss Fire Station!

Traveling South – Via Maine Turnpike, I-95, take Exit 113 to Rte 3 toward Augusta/Belfast. Within 2.5 miles you should turn right at ME-100/US-201 and follow signs for Augusta/Rockland/Camden ME-100/US-201/Rte 17 South. At the traffic circle, take the 3rd exit onto ME 17 South/ ME-9 S, Stone Street. Continue to follow ME-9 South for 6.2 miles. Turn slight left at ME-126/ME-27 and continue on Rte 27 for 18.8 miles. Turn right at Boothbay Road/ Rte 27 and continue approximately 9 miles. You cannot miss Fire Station!

Thursday, March 23, 2017

Pump Maintenance and Troubleshooting

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

MAINE DOT TRAINING CENTER
John E. Dority Safety & Performance Training Center
10 Mountain Ave
Fairfield, Maine 04937
(207) 453-7377

Traveling either North or Southbound - Take I-95 to exit 133

When you come off ramp, head North with the sign saying Jackman/Skowhegan. You will be on Route 201 and as you head north, Dragon Products will be on your right and the first left on Route 201 will be Mountain Ave. Take the first entrance into the parking lot and drive past the main building.

Turn left onto Mountain Ave. DOT is the brick building on the corner of Route 201 & Mountain Ave. There will be a blue & white sign on the lawn that says John E. Dority, Safety and Performance Training Center. Take the first entrance into the parking lot and drive past the main building.

The class will be held in the Lance Gurney building: Look for the sign that says Green Building with a direction arrow to the left. Look for a large green building on the left as you enter a large open parking lot at the top of the hill. Enter through the last door on the right.

Thursday, March 23, 2017

Water & Wastewater Microbiology and Bacteria Tests

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

IDEXX LABORATORIES
1 Idexx Drive
Westbrook, Maine 04092
(800) 548-6733

Travel on the Maine Turnpike (I-95) to Exit 46 – Jetport Exit. When you come off ramp, turn left onto Skyway Drive, then turn left onto Congress Street (Route 22). At the next set of traffic lights, turn right onto Spring Street, then take the first left onto Eisenhower Drive. Idexx Labs will on your left.

Thursday, March 30, 2017

Math Review with Strategies for Operator Certification Exam Success

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

BANGOR WATER POLLUTION CONTROL FACILITY
760 Main Street
Bangor, ME
(207) 942-4111

From I-95: Get off Bangor/Brewer Exit onto Route 395. Get off at the Farm Road Exit 3A. Take left at stop sign onto Farm Rd. Go approximately 100 yards. Take a right at the stop sign (by the Armory) onto Main St. Go underneath railroad overpass - WWTP on the left. Go to the Administration Building.

Wednesday, April 19, 2017

Overview of Drinking Water Distribution Systems

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

Jeff Nixon Development Center
PORTLAND WATER DISTRICT OFFICES
225 Douglass Street
Portland, ME
(207) 774-5961

Southbound from I-295:

Take the Congress St. Exit 5B. Turn right onto Congress Street then immediately take first right onto Douglass St. (Johnson's Sporting Goods on corner of Congress and Douglass Streets). Go to the end. Parking lot is across the street from the training center.

Northbound from I-295: Take Congress St. Exit. After exit, move immediately into right lane and stay right around the clover leaf towards Transportation Center. At end of ramp, stay right onto Fore River Parkway. Go straight through one set of lights and continue on Fore River Parkway to end. **(Hint: Stay in the middle lane because just ahead the two left lanes will have left arrows onto Congress Street, you will want to be in the outside left turning lane).** Turn left on Congress Street then immediately take the first right onto Douglass St. (Johnson's Sporting Goods on corner of Congress and Douglass Streets). Go to the end. Parking lot is across the street from the training center.

Tuesday, April 25, 2017

Biological Nutrient Removal (BNR) With Michael Gerardi

8:30 a.m. - 3:30 p.m.
Sign-in begins at 8:00 a.m.

WELLS RESERVE AT LAUDHOLM
342 Laudholm Farm Road
Wells, ME
(207) 646-1555

Northbound on I-95: Take Exit 19 (Wells) and follow signs to Route 1 in Wells. Follow Route 1 North 1.5 miles to Laudholm Farms Road (just north of the Lighthouse Depot and south of the Maine Diner, at the second flashing traffic signal). Turn right and follow signs to the Reserve.

Southbound on I-95: Take Exit 25 (Kennebunk) and follow signs to Kennebunk. Turn right onto Route 1 and travel 3.3 miles to Laudholm Farm Road (just south of the Maine Diner and just north of the Lighthouse Depot at the flashing traffic signal). Turn left and follow signs to the Reserve.

Wednesday-Thursday, April 26 & 27, 2017

North Country Convention

PRESQUE ISLE INN & CONVENTION CENTER
US Route One
Presque Isle, Maine
(207) 764-3321

Traveling North on I-95, take exit 305. From the exit turn left on to US Route One in Houlton. Stay Straight on US Route One for approximately one hour. Once you enter the town of Presque Isle, you can't miss Presque Isle Inn & Convention Center on the right. If you pass University of Maine at Presque Isle you have gone too far.

Traveling South, take US Route One to Main Street in Presque Isle. Main Street and Route One are the same road. Once you pass University of Maine at Presque Isle look for Presque Isle Inn & Convention Center on the left...You can't miss it!

Tuesday, May 9, 2017

Collection System Diagnosis & Maintenance Series: Part two – Inspection Methods

8:30 a.m. - 3:30 p.m.

Sign-in begins at 8:00 a.m.

MAINE DOT TRAINING CENTER

John E. Dority Safety & Performance Training Center

10 Mountain Ave

Fairfield, Maine 04937

(207) 453-7377

Traveling either North or Southbound - Take I-95 to exit 133

When you come off ramp, head North with the sign saying Jackman/Skowhegan. You will be on Route 201 and as you head north, Dragon Products will be on your right and the first left on Route 201 will be Mountain Ave. Take the first entrance into the parking lot and drive past the main building.

Turn left onto Mountain Ave. DOT is the brick building on the corner of Route 201 & Mountain Ave. There will be a blue & white sign on the lawn that says John E. Dority, Safety and Performance Training Center. Take the first entrance into the parking lot and drive past the main building.

The class will be held in the Lance Gurney building: Look for the sign that says Green Building with a direction arrow to the left. Look for a large green building on the left as you enter a large open parking lot at the top of the hill. Enter through the last door on the right.

Tuesday, May 16, 2017

Confined Space Entry, Line Locating, and Equipment Review

8:30 a.m. - 3:30 p.m.

Sign-in begins at 8:00 a.m.

UNIVERSITY OF MAINE AT FARMINGTON
North Dining Hall C
246 Main Street
Farmington, ME

From the **SOUTH**, Take the Maine Turnpike (I-95) North to Exit 75 at Auburn. (Look for the huge green sign on the Turnpike. Then follow Route 4 North to Farmington.

Or, take the Maine Turnpike (I-95) North to Exit 112B in Augusta. Then follow Route 27 North to Farmington.

From the **WEST**, Just follow U.S. Route 2 East to Farmington.

From the **NORTH** and **EAST**, Take the Maine Turnpike (I-95) to Exit 157 Palmyra/Newport. Then follow U.S. Route 2 West to Farmington.
